



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|-------|------|----------|------|---------|-------|-----|
| PT6A: | -42 | TSN: | 10,494.0 | TSO: | 2,939.5 | W/O#: | N/A |
| PCE: | 94350 | CSN: | 7,563 | CSO: | 2,349 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|------------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3106521 | 8Y545 | 7,563 | 22,437 |
| Disk, 2 nd Stg. | 3023112 | A4022 | 12,324 | 7,676 |
| Disk, 3 rd Stg. | 3023113 | 2K783 | 8,654 | 11,346 |
| Impeller | 3035635 | 5D924 | 7,563 | 12,437 |
| Disk, CT | 3049291-01 | A000675W | 957 | 9,043 |
| PT Disk, 1 st Stg. | 3029312 | 8Y639 | 7,563 | 22,437 |
| PT Disk, 2 nd Stg. | 3029313 | 15A409 | 7,563 | 22,437 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|---------------|--------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | TBA | TBA | 0.0 |
| FUEL PUMP | 025323-300-03 | 10290 | 0.0 |
| FUEL CONTROL UNIT | 3244768-12 | B12564 | 0.0 |
| OIL/FUEL HEATER | TBA | TBA | 0.0 |
| COMP. BLEED VALVE | TBA | TBA | 0.0 |
| COMP. BLEED VALVE | TBA | TBA | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360
 All engines ship FOB ATS dock.