



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|----------------|------|------------|-------|------------|
| PT6A: | -15AG | TSN: | 7,419.8 | TSO: | N/A | W/O#: | TBA |
| PCE: | 14222 | CSN: | N/A | CSO: | N/A | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|--------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 30A010 | 2,085 | 16,915 |
| Disk, 2 nd Stg. | 3013712 | 59A721 | 6,450 | 17,550 |
| Disk, 3 rd Stg. | 3011713 | 59A756 | 5,480 | 19,520 |
| Impeller | 3013176 | 54A153 | 4,102 | 14,898 |
| Disk, CT | 3013411 | 61A030 | 6,918 | 9,082 |
| PT Disk, 1 st Stg. | 3022412 | 4E897 | 3,226 | 16,774 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|---------------|---------|---------|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-002AE | 2334263 | 2,232.7 |
| FUEL PUMP | 025323-101-03 | 14880 | 2,232.7 |
| FUEL CONTROL UNIT | 3244786-6 | B32180 | 2,232.7 |
| START FLOW CONTROL | 3019109 | 14740 | 7,419.8 |
| OIL/FUEL HEATER | 10552E | WA71782 | 7,419.8 |
| COMP. BLEED VALVE | 3100829-03 | 10A585 | 2,232.7 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.