



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	7,991.5	TSO:	0.0	W/O#:	11167
PCE:	RB0278	CSN:	14,739	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA20A995	14,739	4,261
Disk, 2 nd Stg.	3013712	A001XD68	14,739	9,261
Disk, 3 rd Stg.	3011713	TBA	15,000	10,000
Impeller	3013176	EAAA000L798	14,739	4,261
Disk, CT	3013411	TBA	12,000	4,000
PT Disk, 1 st Stg.	3026812	A001XRP0	14,739	5,261
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	14550436	0.0
FUEL PUMP	386100	002364	0.0
FUEL CONTROL UNIT	3244809-8	C25771	0.0
FLOW DIVIDER	25536-4	9959512621	0.0
OIL/FUEL HEATER	10552E	WA23318	0.0
COMP. BLEED VALVE	3100829-03	AHX008971	0.0
Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.			

Comments: All engines ship FOB ATS dock.