



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-135	TSN:	4,154.5	TSO:	696.4	W/O#:	N/A
PCE:	92639	CSN:	3,831	CSO:	632	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9L044	3,831	15,169
Disk, 2 nd Stg.	3013712	9L498	3,831	20,169
Disk, 3 rd Stg.	3011713	7L861	3,831	21,169
Impeller	3013176	6B918	3,831	15,169
Disk, CT	3024211	5L373	3,831	12,169
PT Disk, 1 st Stg.	3022312	3L637	3,831	26,169

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1704533	0.0
FUEL PUMP	025323-101-03	R214D	0.0
FUEL CONTROL UNIT	3244777-6-5	A85159	835
START FLOW CONTROL	3019109A	13311	696
OIL/FUEL HEATER	10552E	1919	696
COMP. BLEED VALVE	3100829-03	2H116	696

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.