



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| <b>Engine Rotor Sheet</b> |               |      |                |      |            |       |             |
|---------------------------|---------------|------|----------------|------|------------|-------|-------------|
| PT6A:                     | <b>-135A</b>  | TSN: | <b>3,549.6</b> | TSO: | <b>0.0</b> | W/O#: | <b>6759</b> |
| PCE:                      | <b>PZ0024</b> | CSN: | <b>6,624</b>   | CSO: | <b>0.0</b> | TSHS: | <b>0.0</b>  |

| <b>Life Limited Part (LLP) Listing</b> |         |          |          |           |
|--|---------|----------|----------|-----------|
|  | P/N     | S/N      | Cycles   |           |
|  |         |          | Consumed | Remaining |
| Hub, 1 <sup>st</sup> Stg.              | 3013111 | 59B383   | 6,624    | 12,376    |
| Disk, 2 <sup>nd</sup> Stg.             | 3013712 | A00045C4 | 6,624    | 17,376    |
| Disk, 3 <sup>rd</sup> Stg.             | 3011713 | A00045B0 | 6,624    | 18,376    |
| Impeller                               | 3027798 | 4H181    | 6,624    | 12,376    |
| Disk, CT                               | 3024211 | A00040L1 | 6,624    | 9,376     |
| PT Disk, 1 <sup>st</sup> Stg.          | 3022312 | A0003K56 | 6,624    | 23,376    |

Key: TBA = To be assigned, N/A = Not Applicable

| <b>Accessories</b> |             |         |     |
|--------------------|-------------|---------|-----|
|                    | P/N         | S/N     | TSO |
| PROPELLER GOVERNOR | 8210-002-01 | 2126827 | 0.0 |
| FUEL PUMP          | 3034792     | 0366    | 0.0 |
| FUEL CONTROL UNIT  | 3244809-8   | C25402  | 0.0 |
| OIL/FUEL HEATER    | 10552E      | WA12650 | 0.0 |
| COMP. BLEED VALVE  | 3100829-03  | 33A280  | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.