



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	13,872.04	TSO:	2,949.58	W/O#:	6724
PCE:	RB0001	CSN:	17,228	CSO:	3,822	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	37W308	10,157	8,843
Disk, 2 nd Stg.	3013712	22B170	17,228	6,772
Disk, 3 rd Stg.	3011713	21B911	17,228	7,772
Impeller	3013176	4F321	17,228	1,772
Disk, CT	3013411	A7423	11,581	4,419
PT Disk, 1 st Stg.	3026812	23B801	17,228	2,772

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	2491437	0.0
FUEL PUMP	3034794	0990	UNKNOWN
FUEL CONTROL UNIT	3244834	C62092	UNKNOWN
OIL/FUEL HEATER	10552E	8950	2,949.58 (TSN)
COMP. BLEED VALVE	3100829-03	22H273	2,949.58 (TSN)

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.