



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-41</b>	TSN:	<b>14,165.8</b>	TSO:	<b>0.0</b>	W/O#:	<b>6748</b>
PCE:	<b>80846</b>	CSN:	<b>13,285</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3021911	3A439	13285	6715
Disk, 2 <sup>nd</sup> Stg.	3023112	A4811	13285	6715
Disk, 3 <sup>rd</sup> Stg.	3023113	B6906	13285	6715
Impeller	3017463	1A618	13285	6715
Disk, CT	3049291-01	A001AH23	3425	6575
PT Disk, 1 <sup>st</sup> Stg.	3058922-01	A001AK2K	3425	4575
PT Disk, 2 <sup>nd</sup> Stg.	3058923-01	A001A1N6	3425	4575

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007	2008233	0.0
FUEL PUMP	025323-300-02	7170	0.0
FUEL CONTROL UNIT	3244755-12	A45318	0.0
OIL/FUEL HEATER	10585 K	WA4600	0.0
COMP. BLEED VALVE	3100922-05	8E980	0.0
COMP. BLEED VALVE	3100923-02	2A109	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.