



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	14,165.8	TSO:	0.0	W/O#:	6748
PCE:	80846	CSN:	13,285	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	3A439	13285	6715
Disk, 2 nd Stg.	3023112	A4811	13285	6715
Disk, 3 rd Stg.	3023113	B6906	13285	6715
Impeller	3017463	1A618	13285	6715
Disk, CT	3024711	TBA	17000	3000
PT Disk, 1 st Stg.	3058922-01	A001AK2K	3425	4575
PT Disk, 2 nd Stg.	3058923-01	A001A1N6	3425	4575

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007	2008233	0.0
FUEL PUMP	025323-300-02	7170	0.0
FUEL CONTROL UNIT	3244755-12	A45318	0.0
OIL/FUEL HEATER	10585 K	WA4600	0.0
COMP. BLEED VALVE	3100922-05	8E980	0.0
COMP. BLEED VALVE	3100923-02	2A109	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.