



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-45R	TSN:	GG: 34,232.2 PS: 33,219.5	TSO:	GG: 0.0 PS: 0.0	W/O#:	6655
PCE:	84020	CSN:	GG: 54,621 PS: 61,666	CSO:	GG: 0.0 PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041611	13B440	10,891	9,109
Disk, 2 nd Stg.	3023112	A000513R	6,065	13,935
Disk, 3 rd Stg.	3023113	A0005153	6,065	13,935
Impeller	3017463	1B366	7,513	12,487
Disk, CT	3024711	6P046	8,201	11,799
PT Disk, 1 st Stg.	3029312	25A986	20,050	9,950
PT Disk, 2 nd Stg.	3029313	17A642	20,050	9,950

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-209F	2242545	0.0
FUEL PUMP	02323-300-03	5011	0.0
FUEL CONTROL UNIT	3244773-5	A83002	0.0
OIL/FUEL HEATER	10585	TBA	0.0
COMP. BLEED VALVE	3100923-02	TBA	0.0
COMP. BLEED VALVE	3123122-01	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.