



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-60AG	TSN:	3,105.3	TSO:	79.7	W/O#:	TBA
PCE:	RG0070	CSN:	N/A	CSO:	N/A	TSHS:	79.7

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041271	A0002X55	3,049	11,951
Disk, 2 nd Stg.	3034312	A0002FMX	3,049	16,951
Disk, 3 rd Stg.	3034313	A000281R	3,049	16,951
Impeller	3036793	4H279	4,156	19,844
Disk, CT	3040311	A0003CPC	2,280	12,720
PT Disk, 1 st Stg.	3029312	A0003AF5	3,053	26,947
PT Disk, 2 nd Stg.	3029313	A0003BOA	3,053	26,947

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-310	12167476	0.0
FUEL PUMP	825601-5	4530	79.7
FUEL CONTROL UNIT	8061-333	12163368	0.0
OIL/FUEL HEATER	10585J	WA12376	0.0
COMP. BLEED VALVE	3117032-01	32A652	79.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.