



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65AR	TSN:	9,322.8	TSO:	0.0	W/O#:	6569
PCE:	97501	CSN:	9,090	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3037101	66B900	6,262	17,738
Shaft Comp. Rotor	3116511-01	77A697	15,533	8,467
Disk, 2 nd Stg.	3036802	21A769	15,871	8,129
Disk, 3 rd Stg.	3036803	18A451	15,871	8,129
Disk 4 th Stg.	3036804	3H835	12,478	11,522
Impeller	3036794	7D639	9,090	14,910
Disk, CT	3040311	22A340	9,090	5,910
PT Disk, 1 st Stg.	3029312	19A111	9,090	20,910
PT Disk, 2 nd Stg.	3029313	6F157	13,068	16,932

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-013J	2477878	0.0
FUEL PUMP	399701-5	1545	0.0
FUEL CONTROL UNIT	8061-329	2138324	0.0
OIL/FUEL HEATER	10585	1788	0.0
COMP. BLEED VALVE	3112714-01	8T753	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.