



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-67D	TSN:	22,598.7	TSO:	0.0	W/O#:	6771
PCE:	114403	CSN:	26,288	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Shaft, Comp. Rotor	3043063	PKAA006A791	6,583	17,417
Disk, 1 st Stg.	3039001	TXA14994	6,583	17,417
Disk, 2 nd Stg.	3040952	EAAA000F902	6,583	17,417
Disk, 3 rd Stg.	3040933	EAAA000K022	6,583	17,417
Disk, 4 th Stg.	3040944	TXA1A5400	6,583	17,417
Impeller	3036898	EAAA000H012	6,583	17,417
Disk, CT	3053740-01	TBA	TBA	4,000
PT Disk, 1 st Stg.	3037312	A001KKMP	6,583	8,417
PT Disk, 2 nd Stg.	3037313	A001L1XB	6,583	8,417

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-410	11497167	0.0
FUEL PUMP	825601-5	3022	0.0
FUEL CONTROL UNIT	8063-005B	11474836	0.0
OIL/FUEL HEATER	10585K	WA6152	0.0
COMP. BLEED VALVE	3123532-01	19A135	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.