



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	7,367.6	TSO:	75.0	W/O#:	3592
PCE:	81576	CSN:	7,013.0	CSO:	52.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3023611	14A220	7,013	12,987
Disk, 2 nd Stg.	3023112	11A552	7,013	12,987
Disk, 3 rd Stg.	3023113	11A553	7,013	12,987
Impeller	3031945	9A311	7,013	12,987
Disk, CT	3049291-01	A000675W	976	9,024
PT Disk, 1 st Stg.	3029312	10A896	3,560	26,440
PT DISK, 2 nd Stg.	3029313	26A735	5,442	24,558

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007F	1208969	75.0
FUEL PUMP	025323-300-03	7214	75.0
FUEL CONTROL UNIT	3244755-14	A62886	75.0
OIL/FUEL HEATER	10585E	430	75.0
COMP. BLEED VALVE	3100922-01	9B713	75.0
COMP. BLEED VALVE	3027651	7B033	75.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.