



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-11	TSN:	5,410.1	TSO:	0.0	W/O#:	6144
PCE:	10005	CSN:	5,036	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	4A679	5,036	13,964
Disk, 2 <sup>nd</sup> Stg.	3013712	3A288	5,036	18,964
Disk, 3 <sup>rd</sup> Stg.	3011713	5A407	5,036	19,964
Impeller	3013176	1A556	5,036	13,964
Disk, CT	3013411	4A205	5,036	10,964
PT Disk, 1 <sup>st</sup> Stg.	3022412	3A348	5,036	14,964

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003H	1440396	0.0
FUEL PUMP	025323-101-2	R349D	0.0
FUEL CONTROL UNIT	3244745-2	A33951	0.0
OIL/FUEL HEATER	10552B	TBA	0.0
COMP. BLEED VALVE	3029174	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable      Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.