



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-112	TSN:	1,741.6	TSO:	N/A	W/O#:	4696
PCE:	12592	CSN:	1,555	CSO:	N/A	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8K816	1,555	17,445
Disk, 2 nd Stg.	3013712	1Y156	1,555	22,445
Disk, 3 rd Stg.	3011713	1Y122	1,555	23,445
Impeller	3013176	3C070	1,555	17,445
Disk, CT	3013411	9N427	1,555	14,445
PT Disk, 1 st Stg.	3031012	2L686	1,555	18,445

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AE	1290097	0.0
FUEL PUMP	025323-150	1110	1,741.6
FUEL CONTROL UNIT	3244745-2	A91252	1,741.6
OIL/FUEL HEATER	10552	4197	1,741.6
COMP. BLEED VALVE	3100829-03A	8F861	729.9

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.