



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	13,639.5	TSO:	0.0	W/O#:	6059
PCE:	17166	CSN:	12,749	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	110859	2,559	16,441
Disk, 2 nd Stg.	3013712	4565	17,857	6,143
Disk, 3 rd Stg.	3011713	4726	17,857	7,143
Impeller	3027798	5E122	14,040	4,960
Disk, CT	3013411	A8386	6,956	9,044
PT Disk, 1 st Stg.	3026812	8T674	12,749	7,251

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2173974	0.0
FUEL PUMP	025323-150	1005	0.0
FUEL CONTROL UNIT	3144809-7-2	B10473	0.0
OIL/FUEL HEATER	10552E	5175	0.0
COMP. BLEED VALVE	3049038-03	GA1024C	NEW

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.