



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|-------|------|---------|------|-----|-------|------|
| PT6A: | -11 | TSN: | 5,410.1 | TSO: | 0.0 | W/O#: | 6144 |
| PCE: | 10005 | CSN: | 5,036 | CSO: | 0.0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 1D627 | 8,352 | 10,648 |
| Disk, 2 nd Stg. | 3013712 | A000P9KM | 4,793 | 19,207 |
| Disk, 3 rd Stg. | 3011713 | A000D3NF | 4,793 | 20,207 |
| Impeller | 3013176 | A8104 | 11,562 | 7,438 |
| Disk, CT | 3013411 | A7164 | 11,562 | 4,438 |
| PT Disk, 1 st Stg. | 3022412 | A3753 | 11,562 | 8,438 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|--------------|---------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-003H | 1440396 | 0.0 |
| FUEL PUMP | 025323-101-2 | R349D | 0.0 |
| FUEL CONTROL UNIT | 3244745-2 | A33951 | 0.0 |
| OIL/FUEL HEATER | 10552B | TBA | 0.0 |
| COMP. BLEED VALVE | 3029174 | TBA | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.