



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-11	TSN:	5,410.1	TSO:	0.0	W/O#:	6145
PCE:	10006	CSN:	5,036	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A0340	11,581	7,419
Disk, 2 nd Stg.	3013712	A1805	11,581	12,419
Disk, 3 rd Stg.	3011713	B1531	11,581	13,419
Impeller	3013176	A8304	11,581	7,419
Disk, CT	3013411	A7423	11,581	4,419
PT Disk, 1 st Stg.	3022412	A4063	11,581	8,419

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003H	1435541	0.0
FUEL PUMP	025323-101	6056	0.0
FUEL CONTROL UNIT	3244745-2	A33333	0.0
OIL/FUEL HEATER	10552B	4096	0.0
COMP. BLEED VALVE	3029174	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.