



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-135	TSN:	3,576	TSO:	0.0	W/O#:	6296
PCE:	92508	CSN:	4,546	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	4B584	3,529	15,471
Disk, 2 nd Stg.	3013712	2D714	3,529	20,471
Disk, 3 rd Stg.	3011713	5F781	3,529	21,471
Impeller	3013176	9A163	3,529	15,471
Disk, CT	3024211	8T069	7,706	8,294
PT Disk, 1 st Stg.	3022312	7N993	14,100	15,900

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1580280	0.0
FUEL PUMP	025323-150	225	0.0
FUEL CONTROL UNIT	3244777-5	C7081	0.0
START FLOW CONTROL	3019109A	10515	0.0
OIL/FUEL HEATER	10552D	1186	0.0
COMP. BLEED VALVE	3100829-03	7C272	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.