



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-21</b>	TSN:	<b>9,527.3</b>	TSO:	<b>0.0</b>	W/O#:	<b>6312</b>
PCE:	<b>24862</b>	CSN:	<b>9,132</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	<b>3013111</b>	<b>1F634</b>	<b>9,132</b>	<b>9,868</b>
Disk, 2 <sup>nd</sup> Stg.	<b>3013712</b>	<b>2D522</b>	<b>9,132</b>	<b>14,868</b>
Disk, 3 <sup>rd</sup> Stg.	<b>3011713</b>	<b>1D084</b>	<b>9,132</b>	<b>15,868</b>
Impeller	<b>3032249</b>	<b>2B010</b>	<b>9,132</b>	<b>9,868</b>
Disk, CT	<b>3013411</b>	<b>7E806</b>	<b>9,132</b>	<b>6,868</b>
PT Disk, 1 <sup>st</sup> Stg.	<b>3022412</b>	<b>9D628</b>	<b>9,132</b>	<b>10,868</b>

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	<b>8210-002</b>	<b>1580146AB</b>	<b>0.0</b>
FUEL PUMP	<b>025323-101-03</b>	<b>9661</b>	<b>0.0</b>
FUEL CONTROL UNIT	<b>3244745-2</b>	<b>A72227</b>	<b>0.0</b>
OIL/FUEL HEATER	<b>10552E</b>	<b>542</b>	<b>0.0</b>
COMP. BLEED VALVE	<b>3100829-03</b>	<b>7C278</b>	<b>0.0</b>

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.