



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	11,102.8	TSO:	0.0	W/O#:	6362
PCE:	52408	CSN:	11,332	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1F703	11,332	7,668
Disk, 2 nd Stg.	3013712	2D694	11,332	12,668
Disk, 3 rd Stg.	3011713	1D098	11,332	13,668
Impeller	3013176	3A188	11,332	7,668
Disk, CT	3013411	8E213	11,332	4,668
PT Disk, 1 st Stg.	3022412	1F525	11,332	8,668

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBA	TBA	0.0
FUEL PUMP	025323-101	9219	0.0
START FLOW CONTROL	3019109	9463	0.0
FUEL CONTROL UNIT	2524440-5	A59708	0.0
OIL/FUEL HEATER	10552E	825	0.0
COMP. BLEED VALVE	3100829-03	A4451	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.