



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	4,949.3	TSO:	0.0	W/O#:	TBD
PCE:	PG0127	CSN:	11,396	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	63B893	11,396	7,604
Disk, 2 nd Stg.	3013712	A000BC5C	11,396	12,604
Disk, 3 rd Stg.	3011713	A000AH3L	11,396	13,604
Impeller	3013176	5H280	11,396	7,604
Disk, CT	3013411	A000BHEM	11,396	4,604
PT Disk, 1 st Stg.	3026812	A000BE0R	11,396	8,604

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1436219	0.0
FUEL PUMP	3034794	1297	0.0
FUEL CONTROL UNIT	2524440-7-6	A7973	0.0
START FLOW CONTROL	3019109 E	15100	0.0
OIL/FUEL HEATER	10552	TBA	0.0
COMP. BLEED VALVE	3029174	80653	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.