



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|-----------------|---|------------|-------|-------------|
| PT6A: | -34AG | TSN: | 10,315.6 | <small>Time since ATS Light OVH</small> | 0.0 | W/O#: | 6078 |
| PCE: | 52250 | CSN: | 10,748.5 | <small>Cycles since ATS Light OVH</small> | 0.0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|-------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 8R641 | 3,353 | 15,647 |
| Disk, 2 nd Stg. | 3013712 | 8T377 | 14,456 | 9,544 |
| Disk, 3 rd Stg. | 3011713 | 7L970 | 5,524 | 19,476 |
| Impeller | 3013176 | 7B243 | 4,266 | 14,774 |
| Disk, CT | 3013411 | 8X147 | 9,193 | 6,807 |
| PT Disk, 1 st Stg. | 3022412 | 3E654 | 9,390 | 10,610 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|---------------------------|-------------|----------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-002-01 | 13018087 | 0.0 |
| FUEL CONTROL UNIT | 3244786-6 | C22039 | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.