



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	9,040.8	TSO:	2,961.9	W/O#:	6297
PCE:	80157	CSN:	10,522	CSO:	2,950	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	9936	10,522	9,478
Disk, 2 nd Stg.	3023112	A2925	10,522	9,478
Disk, 3 rd Stg.	3023113	B0167	10,522	9,478
Impeller	3017463	A1901	10,522	9,478
Disk, CT	3049291-01	A000675W	957	9,043
PT Disk, 1 st Stg.	3022812	1C940	6,194	1,806
PT Disk, 2 nd Stg.	3022813	5D054	6,194	1,806

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
FUEL PUMP	025323-300-02	6177	2,961
FUEL CONTROL UNIT	3244755-20-14-13	A45031	2,961
OIL/FUEL HEATER	10585E	222	2,133

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360
 All engines ship FOB ATS dock.