



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	7,336.9	TSO:	44.3	W/O#:	3592
PCE:	81576	CSN:	6,994	CSO:	33.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3023611	14A220	6,994	13,006
Disk, 2 nd Stg.	3023112	11A552	6,994	13,006
Disk, 3 rd Stg.	3023113	11A553	6,994	13,006
Impeller	3031945	9A311	6,994	13,006
Disk, CT	3049291-01	A000675W	957	9,043
PT Disk, 1 st Stg.	3029312	10A896	3,541	26,459
PT DISK, 2 nd Stg.	3029313	26A735	5,423	24,577

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007F	1208969	44.3
FUEL PUMP	025323-300-03	7214	44.3
FUEL CONTROL UNIT	3244755-14	A62886	44.3
OIL/FUEL HEATER	10585E	430	44.3
COMP. BLEED VALVE	3100922-01	9B713	44.3
COMP. BLEED VALVE	3027651	7B033	44.3

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.