



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	11,451.5	TSO:	2,227	W/O#:	N/A
PCE:	93242	CSN:	11,481	CSO:	2,166	TSHS:	302.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041501	35B664	5,675	24,325
Disk, 2 nd Stg.	30231121	A001LR37	2,166	17,834
Disk, 3 rd Stg.	3021113	A001L6YM	2,166	17,834
Impeller	3017463	1B233	11,481	8,519
Disk, CT	3049291-01	A001LX9W	2,166	7,834
PT Disk, 1 st Stg.	3029312	A000KHXY	6,388	23,612
PT Disk, 2 nd Stg.	3029313	58A808	14,675	15,325

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024H	1715065	2,227
FUEL PUMP	025323-300-03	7987	2,227
FUEL CONTROL UNIT	3244768-13	A697778	2,227
FLOW DIVIDER	25536	4144	2,227
OIL/FUEL HEATER	10585E	706	2,227
COMP. BLEED VALVE	3123122-01	8E524	UNKNOWN
COMP. BLEED VALVE	3123123-01	6E011	UNKNOWN

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360.
 All engines ship FOB ATS dock.