



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	10,494.0	TSO:	0.0	W/O#:	N/A
PCE:	94350	CSN:	7,563	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3106521	8Y545	7,563	22,437
Disk, 2 nd Stg.	3023112	A4022	12,324	7,676
Disk, 3 rd Stg.	3023113	2K783	8,654	11,346
Impeller	3035635	5D924	7,563	12,437
Disk, CT	3024711	7Y953	7,563	12,437
PT Disk, 1 st Stg.	3029312	8Y639	7,563	22,437
PT Disk, 2 nd Stg.	3029313	15A409	7,563	22,437

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBA	TBA	0.0
FUEL PUMP	025323-300-03	10290	0.0
FUEL CONTROL UNIT	3244768-12	B12564	0.0
OIL/FUEL HEATER	TBA	TBA	0.0
COMP. BLEED VALVE	TBA	TBA	0.0
COMP. BLEED VALVE	TBA	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.