



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-42	TSN:	10,494.0	TSO:	2,939.5	W/O#:	6410
PCE:	94350	CSN:	7,563	CSO:	2,349	TSHS:	0.0

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3106521	8Y545	7,563	22,437
Disk, 2 <sup>nd</sup> Stg.	3023112	A4022	12,324	7,676
Disk, 3 <sup>rd</sup> Stg.	3023113	2K783	8,654	11,346
Impeller	3035635	5D924	7,563	12,437
Disk, CT	3049291-01	A000675W	957	9,043
PT Disk, 1 <sup>st</sup> Stg.	3029312	8Y639	7,563	22,437
PT Disk, 2 <sup>nd</sup> Stg.	3029313	15A409	7,563	22,437

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024	1715120	0.0
FUEL PUMP	025323-300-03	10290	0.0
FUEL CONTROL UNIT	3244768-12	B12564	0.0
OIL/FUEL HEATER	3035063	1454	Time Continued
COMP. BLEED VALVE	3100922-05	5K0H	Time Continued
COMP. BLEED VALVE	3100923-02	2K881	Time Continued

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360  
 All engines ship FOB ATS dock.