



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65B	TSN:	6,694.6	TSO:	0.0	W/O#:	4632
PCE:	32290	CSN:	9,611	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3033601	1W405	5,745	18,255
Disk, 2 nd Stg.	3033512	4W955	5,745	18,255
Disk, 3 rd Stg.	3033513	6W700	5,745	18,255
Disk, 4 th Stg.	3033514	4W006	5,745	18,255
Spacer, 4 th Stg.	3107098-01	13B894	5,745	18,255
Impeller	3036039	8C420	5,745	18,255
Disk, CT	3036711	3W122	5,745	9,255
PT Disk, 1 st Stg.	3029312	5W628	5,745	24,255
PT Disk, 2 nd Stg.	3029313	4W338	5,745	24,255

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-046	2248052	794.8
FUEL PUMP	3033808	0963	388
FUEL CONTROL UNIT	8061-318	2020097	484.5
COMP. BLEED VALVE	3106870-01	3N672	UNKNOWN

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.
 This engine can be converted to 65R/AR configuration per PWC Service Bulletin(s). Contact ATS for additional information.