



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	10,866.6	TSO:	0.0	W/O#:	8644
PCE:	17405	CSN:	12,093	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1Y637	12,093	6,907
Disk, 2 nd Stg.	3013712	1A890	17,750	6,250
Disk, 3 rd Stg.	3011713	6487	18,905	6,095
Impeller	3027798	7E420	13,734	5,266
Disk, CT	3013411	A9347	15,024	976
PT Disk, 1 st Stg.	3026812	A5845	19,229	771

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AE	2476713	0.0
FUEL PUMP	3034792	0249	0.0
FUEL CONTROL UNIT	3244809-7-4	B10614	0.0
FLOW DIVIDER	3019906/25536-4	12855	180.7
OIL/FUEL HEATER	10552E	1276	0.0
COMP. BLEED VALVE	3049038-03	GA1151	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.