



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	GG: 14,941.4 PS: 15,042.9	TSO:	GG: 0.0 PS: 0.0	W/O#:	<b>8360</b>
PCE:	<b>RB0001</b>	CSN:	GG: 17,713 PS: 17,763	CSO:	GG: 0.0 PS: 0.0	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	37W308	11,389	7,611
Disk, 2 <sup>nd</sup> Stg.	3013712	22B170	18,460	5,540
Disk, 3 <sup>rd</sup> Stg.	3011713	21B911	18,460	6,540
Impeller	3013176	TBA	12,800	6,200
Disk, CT	3013411	TBA	12,000	4,000
PT Disk, 1 <sup>st</sup> Stg.	3026812	A001209X	11,199	8,801

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1990858	0.0
FUEL PUMP	3034794	0990	0.0
FUEL CONTROL UNIT	3244777-1	A89119	0.0
START FLOW CONTROL	3019109	TBA	0.0
OIL/FUEL HEATER	10552E	8950	0.0
COMP. BLEED VALVE	3100829-03	8C713	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.