



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-41</b>	TSN:	<b>6,008.4</b>	TSO:	<b>0.0</b>	W/O#:	<b>7127</b>
PCE:	<b>80434</b>	CSN:	<b>5,320</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3021911	A3199	5,320	14,680
Disk, 2 <sup>nd</sup> Stg.	3023112	A3996	5,320	14,680
Disk, 3 <sup>rd</sup> Stg.	3023113	B4188	5,320	14,680
Impeller	3017463	4A020	9,466	10,534
Disk, CT	3049291-01	YUAA001A912	391	9,609
PT Disk, 1 <sup>st</sup> Stg.	3029312	17B914	3,701	26,299
PT Disk, 2 <sup>nd</sup> Stg.	3029313	16B029	3,701	26,299

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1995912	0.0
FUEL PUMP	025323-300	5769	0.0
FUEL CONTROL UNIT	3244755-22-21-14	A45294	0.0
OIL/FUEL HEATER	10585	538	0.0
LP COMP. BLEED VALVE	3100923-02	9B847	0.0
HP COMP. BLEED VALVE	3100922-05	24136	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.