



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	6,008.4	TSO:	0.0	W/O#:	7127
PCE:	80434	CSN:	5,320	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	A3199	5,320	14,680
Disk, 2 nd Stg.	3023112	A3996	5,320	14,680
Disk, 3 rd Stg.	3023113	B4188	5,320	14,680
Impeller	3017463	93A288	5,320	14,680
Disk, CT	3049291-01	YUAA001A912	391	9,609
PT Disk, 1 st Stg.	3029312	17B914	3,701	26,299
PT Disk, 2 nd Stg.	3029313	16B029	3,701	26,299

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1995912	0.0
FUEL PUMP	025323-300	5769	0.0
FUEL CONTROL UNIT	3244755-22-21-14	A45294	0.0
OIL/FUEL HEATER	10585	538	0.0
LP COMP. BLEED VALVE	3100923-02	9B847	0.0
HP COMP. BLEED VALVE	3100922-05	24136	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.