



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	9,473.1	TSO:	0.0	W/O#:	7894
PCE:	24568	CSN:	7,433	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA15A690	14,336	4,664
Disk, 2 nd Stg.	3013712	5M755	18,200	5,800
Disk, 3 rd Stg.	3011713	6496	18,521	6,479
Impeller	3013176	EAAA000L503	14,336	4,664
Disk, CT	3013411	8Y429	9,662	6,338
PT Disk, 1 st Stg.	3022412	2L507	14,354	5,646

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	1442043AC	0.0
FUEL PUMP	025323-101-02	7716	0.0
FUEL CONTROL UNIT	3244745-2	A75306	0.0
FLOW DIVIDER	25536	1818	0.0
OIL/FUEL HEATER	10552E	1084	0.0
COMP. BLEED VALVE	3100829-03	1C987	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.