



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	16,072.5	TSO:	0.0	W/O#:	7291
PCE:	PG0113	CSN:	27,042	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1st Stg.	3013111	4K707	9,076	9,924
Disk, 2nd Stg.	3013712	7H605	9,076	14,924
Disk, 3rd Stg.	3011713	7H967	9,076	15,924
Impeller	3013176	6B224	6,940	12,060
Disk, CT	3013411	TBA	11,000	5,000
PT Disk, 1st Stg.	3022412	4A410	7,433	12,567

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1480388	0.0
FUEL PUMP	025323-101-03	13284	0.0
FUEL CONTROL UNIT	2524440-7-6	A74840	0.0
START FLOW CONTROL	3019109	13904	0.0
OIL/FUEL HEATER	10552E	WA6368	0.0
COMP. BLEED VALVE	3100829-03	A-4496	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.