



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	10,177.9	TSO:	2,484.8	W/O#:	7936
PCE:	50815	CSN:	16,428	CSO:	3,999	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8151	16,428	2,572
Disk, 2 nd Stg.	3013712	6Y726	16,260	7,740
Disk, 3 rd Stg.	3011713	9986	16,428	8,572
Impeller	3013176	A1514	16,428	2,572
Disk, CT	3013411	A000KX3Y	12,809	3,191
PT Disk, 1 st Stg.	3022412	9473	16,428	3,572

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	2123420	2,736.1
FUEL PUMP	025323-101-02	2890	1,881.7
START FLOW CONTROL	3019109	11734	607.8
FUEL CONTROL UNIT	2524440-7-6	A74761	607.8
OIL/FUEL HEATER	10552E	4473	600.5
COMP. BLEED VALVE	3100829-03	A9442	607.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.