



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	GG: 17,516.3 PS: 7,764.3	TSO:	GG: 0.0 PS: 0.0	W/O#:	<b>8534</b>
PCE:	GG: 40529 PS: 51843-100	CSN:	GG: 20,475 PS: 9,545	CSO:	GG: 0.0 PS: 0.0	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	82A080	7,795	11,205
Disk, 2 <sup>nd</sup> Stg.	3013712	70A326	11,993	12,007
Disk, 3 <sup>rd</sup> Stg.	3011713	4E171	13,745	11,255
Impeller	3013176	B0833	7,199	11,801
Disk, CT	3013411	9F118	6,150	9,850
PT Disk, 1 <sup>st</sup> Stg.	3022412	8A417	9,545	10,455

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	TBA	0.0
FUEL PUMP	025323-101-03	TBA	0.0
FUEL CONTROL UNIT	3524440-7	TBA	0.0
START FLOW CONTROL	3019109	TBA	0.0
OIL/FUEL HEATER	10552	192	0.0
COMP. BLEED VALVE	3100829-03	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.