



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	10,872.3	TSO:	1,811.3	W/O#:	8782
PCE:	81967	CSN:	9,171	CSO:	1,948	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3021911	5E514	9,171	10,829
Disk, 2 nd Stg.	3023112	6E351	9,171	10,829
Disk, 3 rd Stg.	3023113	A002CB71	1,948	18,052
Impeller	3035635	8C953	7,563	12,437
Disk, CT	3049291-01	A002CAYB	1,948	8,052
PT Disk, 1 st Stg.	3059822-01	A002ALLB	1,948	6,052
PT Disk, 2 nd Stg.	3059823-01	A002CB03	1,948	6,052

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007	1712416	1,811.3
FUEL PUMP	025323-300-03	7669	1,811.3
FUEL CONTROL UNIT	3244755-22-21-19-17	A7723	1,811.3
OIL/FUEL HEATER	10585K	589	1,811.3
COMP. BLEED VALVE	3100922-05	5D506	0.0
COMP. BLEED VALVE	3027631	1D898	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.