



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	13,489.2	TSO:	1,759.8	W/O#:	8903
PCE:	51543	CSN:	12,785	CSO:	1,421	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A4360	12,785	6,215
Disk, 2 nd Stg.	3013712	A001F975	5,882	18,118
Disk, 3 rd Stg.	3011713	A001F9H8	5,882	19,118
Impeller	3013176	6B374	10,685	8,315
Disk, CT	3013411	2D133	4,088	11,912
PT Disk, 1 st Stg.	3022412	A6923	12,785	7,215

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1435713	0.0
FUEL PUMP	025323-101-03	8896	1,265.1
FUEL CONTROL UNIT	2524440-9-8-6	25837	1,265.1
START FLOW CONTROL	25234-3	9897	1,759.8
OIL/FUEL HEATER	10552E	3727	1,759.8
COMP. BLEED VALVE	3100829-03 RE71	2196	1,759.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.