



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	10,165.4	TSO:	3,545.1	W/O#:	8881
PCE:	93069	CSN:	12,172	CSO:	4,200	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3053921-01	TXA1B1339	4,200	15,800
Disk, 2 nd Stg.	3023112	4F881	12,172	7,828
Disk, 3 rd Stg.	3023113	3F986	12,172	7,828
Impeller	3017463	9A916	12,172	7,828
Disk, CT	3049291-01	A0025TYF	4,200	5,800
PT Disk, 1 st Stg.	3058922-01	A0024CBE	4,200	3,800
PT Disk, 2 nd Stg.	3058923-01	A00239HX	4,200	3,800

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1744326	3,545.1
FUEL PUMP	025323-300-03	8157RE50	3,545.1
FUEL CONTROL UNIT	3244768-13	A69196	3,545.1
OIL/FUEL HEATER	10585K-FGHJ	937	3,545.1
LP COMP. BLEED VALVE	3100923-02	5E630	3,545.1
HP COMP. BLEED VALVE	3100922-05	AX636	3,545.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.