



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-42	TSN:	10,514.5	TSO:	3,545.1	W/O#:	8882
PCE:	93112	CSN:	13,192	CSO:	4,200	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3053921-01	TXA1B0335	4,200	15,800
Disk, 2 nd Stg.	3023112	4F988	13,192	6,808
Disk, 3 rd Stg.	3023113	4F060	13,192	6,808
Impeller	3017463	9A998	13,192	6,808
Disk, CT	3049291-01	A0025TYT	4,200	5,800
PT Disk, 1 st Stg.	3058922-01	A00251BK	4,200	3,800
PT Disk, 2 nd Stg.	3058923-01	A002429F	4,200	3,800

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-007G	1744343	3,545.1
FUEL PUMP	025323-300-03	8248	3,545.1
FUEL CONTROL UNIT	3244768-13	A69199	3,545.1
OIL/FUEL HEATER	10585K-FGHJ	1334	3,545.1
LP COMP. BLEED VALVE	3100923-02	2A297	3,545.1
HP COMP. BLEED VALVE	3100922-05	1A592	3,545.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.