



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	5,968.7	TSO:	2,369.3	W/O#:	9070
PCE:	PC1212	CSN:	9,964	CSO:	3,864	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA12A887	9,964	9,036
Disk, 2 nd Stg.	3013712	A001NW2P	9,964	14,036
Disk, 3 rd Stg.	3011713	A001NMY2	9,964	15,036
Impeller	3027798	TXA1A6631	9,964	9,036
Disk, CT	3013411	A001P69H	9,964	6,036
PT Disk, 1 st Stg.	3026812	A001P7P5	9,964	10,036

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	15738602	2,369.3
FUEL PUMP	702801-5	001073	2,369.3
FUEL CONTROL UNIT	3244897-4	C65812	2,369.3
FLOW DIVIDER/DUMP VALVE	3019906/25536-4	18747	Unknown
OIL/FUEL HEATER	10552E	290	2,369.3
COMP. BLEED VALVE	3049038-03	4569	2,369.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.