



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	25,806.7	TSO:	0.0	W/O#:	9181
PCE:	40434	CSN:	27,608	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1D636	10,411	8,589
Disk, 2 nd Stg.	3013712	21A016	15,945	8,055
Disk, 3 rd Stg.	3011713	A0005HKT	10,895	14,105
Impeller	3032249	2B155	11,019	7,981
Disk, CT	3013411	A000EER3	10,235	5,765
PT Disk, 1 st Stg.	3022412	6A395	11,692	8,308

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	19200099	0.0
FUEL PUMP	025323-101-03	14525	0.0
FUEL CONTROL UNIT	2524440-7-6	A89473	0.0
START FLOW CONTROL	3019109	8876	0.0
OIL/FUEL HEATER	10552E	2506	0.0
COMP. BLEED VALVE	3100829-03	4B706	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.