



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| Engine Rotor Sheet | | | | | | | |
|---------------------------|--------------|------|-----------------|------|------------|-------|-------------|
| PT6A: | -34 | TSN: | 25,806.7 | TSO: | 0.0 | W/O#: | 9181 |
| PCE: | 40434 | CSN: | 27,608 | CSO: | 0.0 | TSHS: | 0.0 |

| Life Limited Part (LLP) Listing | | | | |
|--|---------|----------|----------|-----------|
| | P/N | S/N | Cycles | |
| | | | Consumed | Remaining |
| Hub, 1 st Stg. | 3013111 | 1D636 | 10,411 | 8589 |
| Disk, 2 nd Stg. | 3013712 | 21A016 | 15,945 | 8,055 |
| Disk, 3 rd Stg. | 3011713 | A0005HKT | 10,895 | 14,105 |
| Impeller | 3032249 | 2B155 | 11,019 | 7,981 |
| Disk, CT | 3013411 | A000EER3 | 10,235 | 5,765 |
| PT Disk, 1 st Stg. | 3022412 | 6A395 | 11,692 | 8,308 |

Key: TBA = To be assigned, N/A = Not Applicable

| Accessories | | | |
|--------------------|---------------|----------|-----|
| | P/N | S/N | TSO |
| PROPELLER GOVERNOR | 8210-002-01 | 19200099 | 0.0 |
| FUEL PUMP | 025323-101-03 | 14525 | 0.0 |
| FUEL CONTROL UNIT | 2524440-7-6 | A89473 | 0.0 |
| START FLOW CONTROL | 3019109 | 8876 | 0.0 |
| OIL/FUEL HEATER | 10552E | 2506 | 0.0 |
| COMP. BLEED VALVE | 3100829-03 | 4B706 | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.