



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27I-28	TSN:	17,237.2	TSO:	2,660.1	W/O#:	9211
PCE:	51008	CSN:	23,886	CSO:	6,635	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8D567	14,312	4,688
Disk, 2 nd Stg.	3013712	8E779	12,073	11,927
Disk, 3 rd Stg.	3011713	3168	23,585	1,415
Impeller	3013176	2D973	9,092	9,908
Disk, CT	3013411	A8151	12,932	3,068
PT Disk, 1 st Stg.	3026812	23B158	18,497	1,503

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1485612	66.8
FUEL PUMP	025323-101-03	12376	507.3
FUEL CONTROL UNIT	2524440-7-6	A48557	168.0
START FLOW CONTROL	3019109	12047	875.3
OIL/FUEL HEATER	10552E	WA12126	66.8
COMP. BLEED VALVE	3100829-03	1A161	875.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.