



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	-27/-28	TSN:	10,441.5	TSO:	0.0	W/O#:	TBA
PCE:	51636	CSN:	12,132	CSO:	0.0	TSHS:	0.0

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	2A150	12,132	6,868
Disk, 2 <sup>nd</sup> Stg.	3013712	1A861	12,132	11,868
Disk, 3 <sup>rd</sup> Stg.	3011713	1A635	12,132	12,868
Impeller	3013176	1A046	12,132	6,868
Disk, CT	3013411	1A045	12,132	3,868
PT Disk, 1 <sup>st</sup> Stg.	3022412	2A319	12,132	7,868

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003-01	1495653	0.0
FUEL PUMP	025323-101-03	103D	0.0
FUEL CONTROL UNIT	2524440-9	A7406	0.0
START FLOW CONTROL	3019109A	7636	0.0
OIL/FUEL HEATER	10552E	4722	0.0
COMP. BLEED VALVE	3100829-03	3A306	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.