



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	12,101.3	TSO:	1,234.7	W/O#:	9168
PCE:	17405	CSN:	14,074	CSO:	1,981	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1Y637	14,074	4,926
Disk, 2 nd Stg.	3013712	1A890	19,731	4,269
Disk, 3 rd Stg.	3011713	6487	20,866	4,114
Impeller	3027798	7E420	15,715	3,285
Disk, CT	3013411	5D968	13,131	2,869
PT Disk, 1 st Stg.	3026812	23B801	19,346	654

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2476713	1,234.7
FUEL PUMP	702801-5	0249	1,234.7
FUEL CONTROL UNIT	3244809-8	C25593	2,2961.7 (TSN)
FLOW DIVIDER	3019906/25536-4	12855	1,234.7
OIL/FUEL HEATER	10552E	1276	1,234.7
COMP. BLEED VALVE	3049038-03	GA1151	1,234.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.