



**Airforce Turbine Service**  
**www.PT6A.aero**

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-114A</b>	TSN:	<b>14,789.0</b>	TSO:	<b>0.0</b>	W/O#:	<b>9139</b>
PCE:	<b>PC0608</b>	CSN:	<b>24,346</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	RWA28B689	6,581	12,419
Disk, 2 <sup>nd</sup> Stg.	3013712	A002CWR5	6,581	17,419
Disk, 3 <sup>rd</sup> Stg.	3011713	A001RCYW	6,581	18,419
Impeller	3027798	EAAB000K633	6,581	12,419
Disk, CT	3013411	YUAA007A387	1,813	14,187
PT Disk, 1 <sup>st</sup> Stg.	3026812	A001XL001	14,990	5,010

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-1	12247983	0.0
FUEL PUMP	702801-5	0301A	0.0
FUEL CONTROL UNIT	3244897-4	TBA	0.0
FLOW DIVIDER	3019906/25536-4	4822	0.0
OIL/FUEL HEATER	10552E	WA11195	0.0
COMP. BLEED VALVE	3049038-02	91290353	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.