



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	14,789.0	TSO:	0.0	W/O#:	9139
PCE:	PC0608	CSN:	24,346	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA28B689	6,581	12,419
Disk, 2 nd Stg.	3013712	A002CWR5	6,581	17,419
Disk, 3 rd Stg.	3011713	A001RCYW	6,581	18,419
Impeller	3027798	TXA1A9511	877	18,123
Disk, CT	3013411	YUAA007A387	1,813	14,187
PT Disk, 1 st Stg.	3026812	A001XL001	14,990	5,010

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-1	12247983	0.0
FUEL PUMP	702801-5	0301A	0.0
FUEL CONTROL UNIT	3244897-4	TBA	0.0
FLOW DIVIDER	3019906/25536-4	4822	0.0
OIL/FUEL HEATER	10552E	WA11195	0.0
COMP. BLEED VALVE	3049038-02	91290353	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.