



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	10,914.0	TSO:	3,217.9	W/O#:	7968
PCE:	50815	CSN:	16,710	CSO:	4,281	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8151	16,710	2,290
Disk, 2 nd Stg.	3013712	6Y726	16,542	7,458
Disk, 3 rd Stg.	3011713	9986	16,710	8,290
Impeller	3013176	A3980	16,432	2,568
Disk, CT	3013411	A000KX3Y	13,091	2,909
PT Disk, 1 st Stg.	3022412	9473	16,710	3,290

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1485575	580.1
FUEL PUMP	025323-101-02	2890	2,617.8
START FLOW CONTROL	3019109	11734	1,343.9
FUEL CONTROL UNIT	2524440-7-6	A74761	1,343.9
OIL/FUEL HEATER	10552E	4473	1,333.9
COMP. BLEED VALVE	3100829-03	A9442	1,343.9

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.